

Description	Fully automatic welding helmet (no manual adjustment necessary) with true color view, ADF with shade level range 4/5-13 with autopilot.		
Shade levels	inactive:	Shade level 4	
	active:	Shade level 5-13	
Autopilot	ADF with shade level range 4/5-13 with autopilot (automatic shade level adjustment), +/- 2 individual manual offset		
Manual mode	Continuous external adjustment in two shade level ranges 5-9 and 9-13		
Sensitivity	Continuously adjustable, new with "Super High" sensitivity		
Grind mode	External adjustment, shade level 4		
Twilight function	Patented twilight adjustment, adjustable from 0.1 to 2.0 seconds.		
Switching time	light to dark: 0.170 ms at room temp 0.110 ms at 55 °C / 137		
	dark to light: 0.1 s - 2.0 s (with twilig	ht function)	
Classification	Optical class:		1
	Scattered light:		1
	Homogeneity:		1
	Angular dependence:		1
Power supply	Solar cells, 2 pcs batte exchangeable (CR2032		
Operating time batteries	Approx. 3,000 hours (o	operating)	

Sensors	movable sensor slider	
Field of view	50 x 100 mm / 1.97 x 3.94"	
Shape stability	Welding mask: up to 220 °C / 428 °F	
	Front cover lens: up to 137 °C / 279 °F	
Eye protection	Ultraviolet / Infrared Protection: maximum protection at any shade level	
Operating temperature	-10°C to + 70°C / 14°F to 158°F	
Storage temperature	-20°C to + 80°C / -4°F to 176°F	
Weight	500g / 17.6 oz	
Application ranges	Any electric arc welding process Electrode Welding (Stick Welding, SMAW) / MIG / MAG (GMAW) / GMAW High melting rate process / Flux Cored Wire Welding / TIG welding (GTAW) / Plasma Arc Welding / Plasmacutting & Oxy-gas Welding Prohibited for laser welding!	
Scope of delivery	Welding helmet, instruction manual, storage bag, batteries, warranty card and one front cover lens	
Standards	CE, ANSI, EAC, AS/NZS, complies with CSA Z94.3	
Warranty	2 years (except batteries)	
	1 year warranty extension for online product registration within the first 6 months. http://register.optrel.com	